

CERTIFICATE OF COMPLIANCE

Certificate Number 20180104-E335090
Report Reference E335090-20101014
Issue Date 2018-JANUARY-04

Issued to: TAE YANG TRAY CO LTD
33-28 Daemyeonghang 1-ro 28beon-gil
Daegot-myeon
Gimpo-si Gyeonggi-do 10041 KOREA

**This is to certify that
representative samples of** CABLE TRAYS
See Next page for Models

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/NFPA 70 - National Electrical Code,
NEMA VE 1 - Metal Cable Tray Systems,
CSA-C22.2 No. 126.1 - Metal Cable Tray Systems

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20180104-E335090
Report Reference E335090-20101014
Issue Date 2018-JANUARY-04

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Product/Models:

Cable Trays, Ladder Type, Cat. Nos. LB95602HA1, LB85602HA1, LBC5602HA1, LB75602HA1, LB65602HA1, LB55602HA1, LBB5602HA1, LB45602HA1, LB35602HA1, LB25602HA1, LBA5602HA1, LB95602HB, LB85602HB, LBC5602HB, LB75602HB, LB65602HB, LB55602HB, LBB5602HB, LB45602HB, LB35602HB, LB25602HB, LBA5602HB, LB95602HA2, LB85602HA2, LBC5602HA2, LB75602HA2, LB65602HA2, LB55602HA2, LBB5602HA2, LB45602HA2, LB35602HA2, LB25602HA2, LBA5602HA2, LB95202HA, LB85202HA, LBC5202HA, LB75202HA, LB6502HA, LB55202HA, LBB5202HA, LB45202HA, LB35202HA, LB25202HA, LBA5202HA, LB95202HB, LB85202HB, LBC5202HB, LB75202HB, LB65202HB, LB55202HB, LBB5202HB, LB45202HB, LB35202HB, LB25202HB, LBA5202HB, LB95202HC, LB85202HC, LBC5202HC, LB75202HC, LB65202HC, LB55202HC, LBB5202HC, LB45202HC, LB35202HC, LB25202HC, LBA5202HC, LB91202HC, LB81202HC, LBC1202HC, LB71202HC, LB61202HC, LB51202HC, LBB1202HC, LB41202HC, LB31202HC, LB21202HC, LBA1202HC, LB95502SA, LB85502SA, LBC5502SA, LB75502SA, LB65502SA, LB55502SA, LBB5502SA, LB45502SA, LB35502SA, LB25502SA, LBA5502SA, LB95202SA, LB85202SA, LBC5202SA, LB75202SA, LB65202SA, LB55202SA, LBB5202SA, LB45202SA, LB35202SA, LB25202SA, LBA5202SA, LB95202SB, LB85202SB, LBC5202SB, LB75202SB, LB65202SB, LB55202SB, LBB5202SB, LB45202SB, LB35202SB, LB25202SB, LBA5202SB, LB95202SC, LB85202SC, LBC5202SC, LB75202SC, LB65202SC, LB55202SC, LBB5202SC, LB45202SC, LB35202SC, LB25202SC, LBA5202SC, AB95423B, AB85423B, ABC5423B, AB75423B, AB65423B, AB55423B, ABB5423B, AB45423B, AB35423B, AB25423B, ABA5423B, AB95423A2, AB85423A2, ABC5423A2, AB75423A2, AB65423A2, AB55423A2, ABB5423A2, AB45423A2, AB35423A2, AB25423A2, ABA5423A2, AB91423B, AB81423B, ABC1423B, AB71423B, AB61423B, AB51423B, ABB1423B, AB41423B, AB31423B, AB21423B, ABA1423B, AB91323C, AB81323C, ABC1323C, AB71323C, AB61323C, AB51323C, ABB1323C, AB41323C, AB31323C, AB21323C, ABA1323C.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

